

*Brinelling on the swash plate bearing surface is common with Rexroth A4V and A11V pumps and Sundstrand 90 series pumps. We at Lapping Services answered the call for help from a number of our clients to repair these expensive components.*



*The two Sundstrand 90series—055 swash plates above have been successfully ground and the final size measured with special measuring equipment sourced from over seas.*





*Lapping Services' employee checking a 90series swash plate with our special measuring equipment*



**Finished!**

*Finished to Lapping Services usual very high standard*

*Bearing surfaces refurbished*



*Unique identification number engraved on all refurbished components*

*We though you could benefit from the services we provided .....*

*Lapping Services; Where The Quality and Service is Worth Remembering*



*The Lapping Innovators*

*Telephone; 08 9358 1686    Mobile; 0407 347 348*